


# Modification to 2003-2005 KTM 950 Adventure to install BDCW new style side stand mount

*A small portion of the frame just below the shifter needs to be removed – easily accomplished with a grinder in a few minutes. Be sure to treat the frame with some type of paint or sealant to prevent rust.*

## BEFORE PHOTOS



# Modification to 2003-2005 KTM 950 Adventure to install BDCW new style side stand mount

## AFTER PHOTOS:

Trimming complete

IMPORTANT: Ensure that the frame piece is trimmed enough to allow the BDCW Side Stand Mount to lay flat against the vertical framework pictured here.

\*\*\* DO NOT CUT OR MODIFY THE BDCW SIDE STAND MOUNT \*\*\*



Underside view of trimming complete



New BDCW side stand mount installed

\*\*Notice applied sealant to prevent rust

